State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

DOZH

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX Co			
Inspection Date & Time	e: 10/25/2001	1 / 10:03 AM to	12:30 PM
Date of Last Ins			

Mine Name: <u>Des Bee Dove Mine</u> County: <u>Emery</u>	Permit Number: <u>C/015/017</u>
Permittee and/or Operator's Name: PacifiCorp	
Business Address: P.O. Box 310, Huntington, Utah 84528	
Type of Mining Activity: Underground XXX Surface	Prep. Plant Other
Company Official(s): <u>Dennis Oakley</u>	
State Official(s): <u>Jim Smith</u> Federal Official(s):	
Weather Conditions: <u>Clear, warm</u>	
Existing Acreage: Permitted <u>2760</u> Disturbed <u>24</u> Reg	graded Seeded
Status: Active XXX	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	EVALUATED [X]	<u>N/A</u> ∐	COMMENTS	NOV/ENF ∐
2.	SIGNS AND MARKERS	<u>[X]</u>	П	[X]	П
3.	TOPSOIL	[X]		[]	
<i>3</i> .	HYDROLOGIC BALANCE:	1211	ц	ш.	-
٠,,	a. DIVERSIONS	П	П	П	[]
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]		<u>[X]</u>	豆
	c. OTHER SEDIMENT CONTROL MEASURES	<u>[X]</u>		<u>[X]</u>	$\overline{\Box}$
	d. WATER MONITORING				$\overline{\square}$
	e. EFFLUENT LIMITATIONS	$\overline{\Box}$	口	$\overline{\square}$	\Box
5.	EXPLOSIVES	$\overline{\Box}$	$\overline{\Box}$	$\overline{\square}$	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\overline{\Box}$	口	$\overline{\square}$	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		$\overline{\Box}$	П	П
8.	NONCOAL WASTE	П		т 📙	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	П	\Box	\Box	\Box
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE	П	\Box		П
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box	П	П
12.	BACKFILLING AND GRADING	\Box	\Box	П	П
13.	REVEGETATION	\Box	\Box	П	П
14.	SUBSIDENCE CONTROL	\Box	\Box	\Box	Ц
15.	CESSATION OF OPERATIONS	\Box	\square	П	Ц
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	<u>∐</u>	\Box	П	П
	b. DRAINAGE CONTROLS	\Box	П	П	Ц
	OTHER TRANSPORTATION FACILITIES	\Box	Ц	П	П
-	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	\Box	П	Ц
	AVS CHECK (4th Quarter- April, May, June)	П	П	П	Ц
	AIR QUALITY PERMIT	\Box	П	Ц	Ц
21.	BONDING & INSURANCE	[X]	П	[X]	\Box

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/017

DATE OF INSPECTION: 10/25/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

Mine entrance signs are in place, legible, and have the necessary information.

Disturbed area boundary markers were spot checked and appear sufficient to identify this boundary. In addition to a simple post or roof-bolt, Energy West places a sign at the top of each marker post or stake: many of the signs are missing due to rust or vandalism - mainly small-arms fire. There are signs in the shop to replace the missing signs, but the posts are sufficient to mark the boundary in the interim.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Pond inspected 4 October 2001 by Rick Callum - surveyor - and John Christensen - PE. Sediment was at 2.57 acre-feet, designed capacity is 2.0 acre-feet. However, the pond is scheduled for clean-out during the 4th quarter.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The ditch around the base of the subsoil pile at the sedimentation pond and the straw bales at the end of that ditch need maintenance to avoid off-site impacts from future precipitation. There was no evidence that sediment had left the permit area as yet.

The silt fence in the road-side ditch, at the hairpin turn between the main mine-site and the old pump-house location, also needs maintenance.

Dennis Oakley stated that maintenance at both areas would be done in the near future.

21. BONDING AND INSURANCE

The bond, for \$1,837,712, is dated July 1, 1994.

The insurance is with Associated Electric and Gas Insurance Services, Limited of Hamilton, Bermuda. General liability is \$2,000,000 and excess liability is \$20,000,000. The notification disclaimer on the Accord form has been modified to show that the Division will be notified in case of cancellation.

Inspector's Signature:

James D. Smith #4

Date: 10/29/2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015017.DBD\Compliance\2001\p_1025.wpd